

AerDocsis System Software Software Release Notes

lomoM12 20.2.7799

August 27th, 2026

Contents

1. Compatible devices and minimum versions.....	3
2. What's new in this release?.....	4
2.1 New Features.....	4
2.1.1 BS450 Base Stations.....	4
2.2 Improvements.....	4
2.2.1 Common to all devices.....	4
2.3 Applied solutions.....	4
2.3.1 Common to all devices.....	4
3. Important notes.....	6
3.1 IMPORTANT NOTE: Radio FW update.....	6

1. Compatible devices and minimum versions

Product family	Devices	Minimum versions
Base Stations		
BS400 and BS800	AXS-BS-450-N AXS-BS-452-N AXS-BS-850-N	HoneybeeM1 19.6.6172

2. What's new in this release?

2.1 New Features

2.1.1 BS450 Base Stations

New products

Support has been added for the new AXS-BS-450-N A28 models.

2.2 Improvements

2.2.1 Common to all devices

Internal

Factory setup processes have been optimized.

2.3 Applied solutions

2.3.1 Common to all devices

Network interface management

If the default policy on the network interfaces was set to DROP, the radios would not start. If this configuration was saved, the problem persisted after rebooting the device.

Provisioning

After deleting a template on the Local AA web interface, the associated users were left with an internal template whose use is reserved for the system, and the option to edit it was available. This is no longer possible.


Radio

Errors in the processing of control messages have been fixed. These could cause important processes to stop, requiring the device to be rebooted in order to become fully operational again.

3. Important notes

3.1 IMPORTANT NOTE: Radio FW update.

After updating to this release and restarting the device, the system will check if it needs to make updates to the radios' firmware, so it may take longer than usual to be fully operational. If these updates are necessary, the system will notify you on the website with a message as shown in the following image:



It is important that the equipment is not turned off electrically until the update is completed. Otherwise, the firmware may be corrupted and it will be necessary to send the device to the factory for manual updating.

The devices that may require this additional update step are the following:

Model	Serial number
AXS-BS-850-N	A24XXX, A22X1X
AXS-BS-452-N	A25XXX, A23X04, A23X05
AXS-BS-450-N	All